



Front and Rear Stator Bushing

The picture above shows the stator for the A340 transmission. The two bushings shown are the front and rear stator bushing. Wear in these two bushing, especially the front bushing can cause the pesky P0770 code. Omega Machine & Tool's bushing is machined to a closer tolerance, giving lasting service.

Your feedback is welcome on all our products!

Omega Machine & Tool, Inc.

"Precision and Innovation for Today"

*** New Address ***

2949 Promenade St # 100
West Sacramento CA 95691
Tel. 800 601 7722 – Fax 916 372 6020
www.omegamachine.com