

45RFE Accumulator plate

The accumulator screws come loose or break, and the OD accumulator piston exits the bore. The plate is damaged beyond repair. In the past the only fix was buying a complete valve body.



Grand Cherokee 4.7L V8 99 - Up
Durango 00 - Up

For more information, inquire at your nearest transmission parts supplier.

Omega Machine & Tool, Inc.

“The Best Kept Secret in the Transmission Industry”