

## Hard Parts

### DESCRIPTION AND SPECIFICATIONS

A44DE forward clutch drum repair ring cut. R&R only Miata 98-99



**R4A-EL governor bore repair.**

## Mercedes

### Bushings


PART NO	DESCRIPTION AND SPECIFICATION
77423	MERCEDES 722.3,5, & 6 FRONT pump body bushing (HUB OF 1.692) 1981-Up. Steel- backed Babbitt (6-bolt pan, 4-speed)
77440	Sun gear bushing for 722.6 transmissions
77413	96-99 Mercedes 722.6 input drum bushing

## Hard Parts

### DESCRIPTION AND SPECIFICATIONS

Mercedes Bell Housing - Replaced stator  
RE-bush and seal ZF pump body  
Repair Mercedes case governor bore

### Omega number MERBH



Mercedes Benz Bell Housings – Fitted with new hardened stator shaft

**18b.**