


## 09G TF60SN C2 Clutch Drum Bushing Repair Tool

The center post at the rear of the 09G case holds a bushing that tends to ruin the case when it spins. In order to save the cases we have produced an oversize bushing.



Machining of the case is necessary to install the bushing. The sleeve at the rear of the case must fit firmly on the post. Three bushings come with the tool. Omega Machine is please to announce this tool so you can repair these cases in house.

Your feedback is welcome on all our products!

**Omega Machine & Tool, Inc.**  
"Precision and Innovation for Today"

Tel. 800 601 7722 – Fax 916 372 6020  
[www.omegachine.com](http://www.omegachine.com)