

## 09G - TF60SN C2 Clutch Drum Bushing Case Repair Part # 90448A BMW 6F21A, VW, Skoda, Seat



## 09G TF60SN C2 Clutch Drum Bushing

This post supports a sealing ring sleeve. Check to be sure the sleeve is tight on the post. The center of the post holds a bushing that tends to ruin the case when it spins. Getting the bushing out is difficult. In order to save the cases we have produced an oversize bushing. Machining of the case is necessary to install the bushing. We machine the cases in-house.

Your feedback is welcome on all our products!

## Omega Machine & Tool, Inc.

"Precision and Innovation for Today"

Tel. 800 601 7722 – Fax 916 928 6020 www.omegamachine.com