

42RE Extension Housing Repair

Grand Cherokee 99-04 Dodge Dakota 04-05 Chrysler 99-04



The extension housing bearing snap ring wears into the case causing the rear bearing to walk back and forth in the case.

We repair the case to take the load off the snap ring

One day service is available.

Your feedback is welcome on all our products!

Omega Machine & Tool, Inc.

"Precision and Innovation for Today"

* New Address *

2949 Promenade St # 100

West Sacramento CA 95691

Tel. 800 601 7722 – Fax 916 372 6020

www.omegamachine.com