


Toyota A246E Case Repair

The center bearing spins in the case distributing fine metal particles throughout the transmission.
Can you say shift problems?



A246E Vehicles

1994-1999 Celica ST, 2003-2007 Matrix, 2003-2008 Pontiac Vibe



“Precision and Innovation for Today”

2949 Promenade St # 100 West Sacramento CA 95691

Tel. 916 372 6001 – Fax 916 372 6020
www.omegachine.com